






GALANT



Design and Quality
IKEA of Sweden



14x

118331



10x

118137
119253



8x

101350




12x

101345



12x

109049




4x

122973
122972




8x

121762




123452

1x




123255

2x




123276

2x




123335

1x




119030
117434

1x




123264

4x




100006

1x




115988

4x




1x

123322




124571

2x




108442

2x




123351

1x



109535

31x



108445

4x




100395

1x




108200

1x




124552

1x




124553

1x




124554

1x




124555

1x




124558

1x




124557

2x




124556

2x




124559


2x











1x








1x





1x





1





2





3




4




5




6




7





8





9




10






11










12




13




14







15




16



17




18




119030
117434


3x



119030
117434




19




119253 119030
118137 117434


2x




119253
118137




20




21





22




23





24






25




26




27





28




29






30







31







32















34




35




36






37





38







39






40










41




42



43






GALANT




Design and Quality
IKEA of Sweden


i





1





2




3



4



5



6

