








# GALANT



Design and Quality  
IKEA of Sweden






118331

16x



123492

2x



124327

2x



101350

14x




101375

2x




122971  
118137  
119081  
119253

16x



1x


120076  
117434  
118224  
119030




105867

1x


1





2




# 3




# 4






5





6




7





8



# 9




# 10







# 11





# 12




# 13




120076  
117434  
118224  
119030




4x




# 14




# 15





16






17









↓  
19





20





21




22










24



25

